

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1

Transducer	Parameter	4*(1-3) 100 Ω
Backing:	Z(MRayl)	2
Metal towards backing:	Z (MRayl) c (m/s) l (μ m)	30 3750 15
Elem. a:	Lsa(μ H) Cca(pF) Rls(a)(Ω) Z^D (MRayl) c (m/s) h (10^9 V/m) ϵ_s l (μ m) Area (mm ²)	6 100 100 14.06 3569 1.626 888 140 3.0 (2 stk.)
Metal between sub-elements:	Z (MRayl) c (m/s) l (μ m)	20 3750 15 (3 stk.)
Elem. b:	Lsb(μ H) Ccb(pF) Rlsb(Ω) Z^D (MRayl) c (m/s) h (10^9 V/m) ϵ_s l (μ m) Area (mm ²)	16 100 100 14.06 3569 1.626 888 116 3.0 (2 stk.)
Metal towards front:	Z (MRayl) c (m/s) l (μ m)	30 3750 15
Transf. 1:	Z(MRayl) $1/\lambda v/2.5MHz$	8.04 0.25
Transf. 2:	Z(MRayl) $1/\lambda v/2.5MHz$	2.63 0.25

Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7: Received first harmonic signal from the pressure in Fig. 5, when using the response B11 in reception.




Fig. 8




Fig. 9






Fig. 10



卷之三




Fig. 13